

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY El Paso Natural Gas Company - Box 997, Farmington, New Mexico
(Address)

LEASE Lindroth Unit WELL NO. 22 UNIT D S 19 T 24N R 2W
DATE WORK PERFORMED 12-18-57 POOL South Blanco P. G.

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Water Fracture

Detailed account of work done, nature and quantity of materials used and results obtained.

Total depth 3145'. Clean out depth 3122'. Water fractured Pictured Cliffs through perforated intervals 3080-3106 w/42,000 gallons water and 40,000# sand. Breakdown pressure 3100#, max. pr. 3100#, avg. tr. pr. 1700, 1600#. IN 67 bbls./min. Flush 4200 gallons.



FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
		(Company) _____

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold
Title Supervisor Dist. # 3
Date JAN 3 1958

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Original Signed D. C. Johnson
Position Petroleum Engineer
Company El Paso Natural Gas Company

OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Received <u>3</u>		
DISTRIBUTION		
Operator	<u>1</u>	
Santa Fe	<u>1</u>	
Production Office		