

(SUBMIT IN TRIPLICATE)

Indian Agency **Jicarilla**
Dulce, New Mexico

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____
Lease No. **Jicarilla Tribal**
Contract No. 37
Tract No. 82

X			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 23, 1957

Well No. **1-23** is located **990** ft. from **[N]** line and **990** ft. from **[E]** line of sec. **23**
NW/4 Section 23 **T-24-N** **R-5-W** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Otero PG (Ext) **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6695** ft. (**6688 GL**)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

While flowing and testing well on April 10th, tubing appeared to be parted. Began remedial work on April 16th. Killing well, pulling tubing, (hole in tubing) washing to bottom, circulating, pulling out, running tubing, swabbing tubing. Well flowing at 4 PM Saturday April 20th. Shut well in for tests.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Ken Blackford**
Address **P. O. Box 1527**
Farmington, New Mexico
By **Ken Blackford**
Title **Operator**

