

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office

Lease No.

Unit

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS SEP 30 1960

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 25

19

Well No. is located 30 ft. from [N] line and 155 ft. from [E] line of sec. 17

NE 1/4 NW 1/4 Sec. 17 T4N 7W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

36000 (Gallatin) Rio Arriba New Mexico  
(Field) (County or Sub-division) (State or Territory)


The elevation of the derrick floor above sea level is 2111 ft. (est.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

7/27/60 - Spudded well. Set 213' of 4 1/2" x 24" pipe. Casing set 100 sacks 50-50 cement 3% calcium chloride. Circulated cement to surface.

28/60 - Drilling ahead from under surface casing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Dorffman Production Company

Address 836 Mercantile Dallas Building

Dallas 1, Texas

By

S. L. Florenheim, Jr.

Title

General Manager