

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 688130
Unit Monice Fed #7

SUNDRY NOTICES AND REPORTS **RECEIVED**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	1
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REPAIRING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Monice Fed #7 June 9, 1960
Well No. 1 is located 1450 ft. from N line and 990 ft. from E line of sec. 9
SW/4 Section 9 24N 14 100W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat - Pictured Cliffs Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 10:30 AM June 30, 1960.
Drilled 12-1/4", hole to 122',
Set 8-5/8" CD casing at 116', cemented with 125 sacks of regular cement.
Cement circulated. Plug down at 6:30 PM June 2, 1960.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stelly Oil Company

Address Box 426

Farmington, New Mexico

By (Signed) P. E. Cospes

Title District Superintendent

RECEIVED
JUN 12 1960
U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C.

100-100000-1000