

X		

(SUBMIT IN TRIPLICATE)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No. 078877
Unit Canyon Largo

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SLOAN-GOVERNMENT #1-11: October 21, 1957

Well No. 1-11 is located 1115 ft. from N line and 1560 ft. from Ex line of sec. 11

SW/4 Section 11 T-24N R-6W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

(Canyon Largo Unit)
The elevation of the derrick floor above sea level is 6413 ft. (KB 6414)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 2216' FBTD: 2185' 7" - 20# Casing cemented to 2216'.

OPEN PERFORATIONS: 2156-2175

Propose to lower 2-1/2" tubing and equalize 20 sax Regular Cement @2185', pull to 1600' and equalize 75 sax. Place 10 sax plug in top of 7" casing. Place a 4' - 4" pipe marker in 7" casing at ground level. Clean up location.

NOTE: Electric Log enclosed

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Superior Oil Company

Address Midland, Texas

By W. J. Mathis (Wm. J. Mathis)

Title Petroleum Engineer



