

(SUBMIT IN TRIPLICATE)

Indian Agency ----- **Navajo**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Jicarilla Tribal
Lease No. Contract 111

			2

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED

MAY 20 1957

U. S. GEOLOGICAL SURVEY

NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 15th.....1957

Well No. 3-H is located 990 ft. from S line and 1090 ft. from E line of sec. 5

SE/4 SE/4 Sec. 5

248

44

N.L.P.N.

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

S. Blanco PC Ext.

No Affixes

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6734 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-13-57 TD 105.9' RKB. Set 3 joints 96' of 8-5/8" OD 32# casing at 105' RKB with 70 sacks cement, circulated to surface.

4-14-57 Pressured up on casing to 500#. No pressure decrease in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **EL PASO NATURAL GAS COMPANY**

Address ~~Box~~ 997

Farmington, New Mexico

By Leigh F. Scott
Title Senior Petroleum Engineer