

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 3 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1 |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Non-Commercial Well | 7. Unit Agreement Name Lindrith Unit |
| 2. Name of Operator El Paso Natural Gas Company | 8. Farm or Lease Name Lindrith Unit |
| 3. Address of Operator Box 990, Farmington, New Mexico | 9. Well No. 21 (P & A) |
| 4. Location of Well UNIT LETTER 0 800 FEET FROM THE South LINE AND 1600 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 24-N RANGE 2-W NMPM. | 10. Field and Pool, or Wildcat So. Blanco P. C. |
| 15. Elevation (Show whether DF, RT, GR, etc.) 7171' G1, 7181' DF | 12. County Rio Arriba |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|---|--|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 5-24-65, this well was plugged and abandoned in the following manner:

Spotted 30 sack cement down tubing, 3305-3354', pulled tubing. Did not recover any 5 1/2" pipe. Spotted 10 sack cement plug in surface with 4" x 4' Plug and Abandonment marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **ORIGINAL SIGNED E. S. OBERLY**

TITLE **Petroleum Engineer**

DATE **June 24, 1965**

Original Signed **Emery C. Arnold**

TITLE **Supervisor Dist. # 3**

DATE **JUN 30 1965**

CONDITIONS OF APPROVAL, IF ANY:



NEW MEXICO OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
Aztec, New Mexico
January 6, 1966

Mr. E. S. Oberly
El Paso Natural Gas Company
Box 990
Farmington, New Mexico

RE: Plugging Reports

Gentlemen:

Form C-103, Notice of Intention to Plug, your Lindrith Unit #21 0-5-24N-2W
Lease Well No. Unit- S-T-R
was approved on April 21, 1965. Your subsequent notice of plugging cannot be
approved until a commission representative has made an inspection of the location
to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done
so that our representative will not have to make more than one trip to the location.

Location inspected
5-4-66
Ea - OK

OIL CONSERVATION COMMISSION

By *Art Bendrick*

Fill in below and return:

Lindrith Unit #21 0-5-24N-2W
Lease Well No. Unit-S-T-R

is ready for your inspection and approval.

Operator

Name and title

16