

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Location AlbuquerqueAllottee Contract # 126

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JUN 28 1956

Well No. 8 1-1 is located 1650 ft. from S line and 1670 ft. from E line of sec. 1

1650 (4 Sec. and Sec. No.) 1670 (Twp.) 1670 (Range) 1670 (Meridian)


Wildcat (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the ungraded ground above sea level is 6829.7 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to 3329' & set 3329.22 of 4 1/2" 9.54 P. 8 RD J & L casing w/ Baker
Float above 3326' & cemented w/ 100 cu of 8 1/2 gal & 75 cu seg w/ 1/2" float etc
p/s. POC 6:30 pm 6-13-56. After 30 hrs WOC, casing tested OK.
Free to water flow.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NORTHWEST PRODUCTION CORPORATIONAddress 500 Glass BuildingAlbuquerque, New MexicoBy Ray Phillips, Jr.Title Asst. Mgr., Production Operations

