

(SUBMIT IN TRIPLICATE)

Indian Agency Jicarilla  
Dulce, New Mexico

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_  
Lease No. Jicarilla Tribal  
Contract No. 13  
Tract No. 21

	X	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OPERATION)  
FARMINGTON, NEW MEXICO

October 27, 1959

Well No. 3-23 is located 1850 ft. from S line and 1850 ft. from W line of sec. 23  
SW/4 Sec 23 T-24-N R-5-W N. M. P. M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Otero PC Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft. 6672 GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded in at 11 A. M. Tuesday October 19th.  
Set 3 joints, 92' 8 5/8 24# JS casing at 94' and  
cemented with 70 sax regular cement. Cement circulated.  
One centrizer run on bottom joint. Plug down at 11 A.M.  
Thursday October 21st.

Tested casing with 500# for 20 minutes. Test of casing  
drilling plug on Tuesday October 27th.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ken Blackford  
Address P. O. Box 1527  
Farmington, New Mexico  
By Ken Blackford  
Title Operator