

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 080472
Unit Callins-Federal

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
SEP 16 1957

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 12, 1957

Well No. 2 is located 1650 ft. from N line and 990 ft. from E line of sec. 4


Sec. 4 (1/4 Sec. and Sec. No.) 24-N (Twp.) 3-W (Range) N.M.P.M. (Meridian)
So. Blaine (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is Est. 7012 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 238' of 4-5/8" Surface Casing on bottom at 238' with 200 cu
casing. Circulated. Tested 4-5/8" Surface Casing with 800' for 30 minutes.
Tested OK. No Break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MACHINIA OIL & LEASE COMPANYAddress P.O. BOX 633MIDLAND, TEXASBy R.T. GLENNTitle Division Superintendent