

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
" " " " Fracture	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 6, 1956

Well No. 1 Spain is located 1075 ft. from $\left\{ \begin{smallmatrix} N \\ 8 \end{smallmatrix} \right\}$ line and 920 ft. from $\left\{ \begin{smallmatrix} E \\ W \end{smallmatrix} \right\}$ line of sec. 3

NE/4 3 24N 4W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
WC Rio Arriba N.M.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6939 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 3220' 4 1/2 casing. Tested @ 1000# for 30 min. No loss.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SPURRIER & BIGBEE

Address Box 784
Santa Fe, New Mexico

By *R. H. Spurrier*
Title Agent