

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 1, 19 56

Well No. 1 Spain is located 1075 ft. from N line and 929 ft. from E line of sec. 3

NE/4 3 24N 4W 100W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
WC Rio Arriba N.M.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6939 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 116' 7 5/8" casing. Tested @ 1000# for 30 minutes - no loss



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SPURRIER & BIGHAM

Address Box 784

Santa Fe, N.M.

By R. R. Spurrier

Title Agent