

(SUBMIT IN TRIPLICATE)

Indian Agency 11084110

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Jicarilla Tribal

Lease No. Contract 111

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Sandfrac

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

FEBRUARY 26th 19**57**

Well No. 1-N is located 990 ft. from N line and 990 ft. from E line of sec. 5

HR/4 HR/4 Sec. 5
(14 Sec. and Sec. No.)

Wildcat

(Field)

24th
(Twp.)

(Twp.)

(Rang

(Range)

Rio Arriba

(County or Subdivision)

(Meridian)

Now \$1.00

(State or Territory)

The elevation of the derrick floor above sea level is 6785 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-20-57 FWD 2989'. Perforated 2895' to 2908' and 2926' to 2938' with 4 holes per foot. Sandfraced with 30,000 gallons water and 30,000# sand, flushed with 3,000 gallons water. Breakdown pressure 3200#, treating pressure 1500-1800#, average injection rate 67.7 barrels per minute.

2-21-57 After 7 hours flowing 1,325 MCF/day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company EL PASO NATURAL GAS COMPANY

Address Box 997

Farmington, New Mexico

By

Title Senior Petroleum Engineer