

0		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Dale
Contract # 125
Allottee _____
Lease No. _____
Arizona-Vicarilla

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Arizona-Vicarilla

October 19, 19 59

Well No. # 4 is located 990 ft. from N line and 990 ft. from W line of sec. 36

N-1 Section 36 T-25N R-10W N.1.P.1.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Plains-Pictured Cliffs Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7291 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Total depth - 3753'
Sand-Water fraced with 42,000 gallons water, 7140 gallons flush, 60,000# sand
Breakdown pressure - 2700
Treating pressure - 2000
I.R. - 41.5 bpm
Final pressure 700
Set 116 joints, 3652' of 2" Tubing, landed at 3653'
Shut in for gauge.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil and Gas Company

Address Box # 786,

Farmington, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON

Title Joe C. Salmon
District Superintendent

