

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. CONTRACT No. 122
2. NAME OF OPERATOR CONTINENTAL OIL COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME JICARILLA APACHE
3. ADDRESS OF OPERATOR Box 460, HOBBS, N. M. 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1450' FNL E 1105' FEL OF SEC. 3		8. FARM OR LEASE NAME AXI APACHE "O"
14. PERMIT NO.		9. WELL NO. 7
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6988' GR.		10. FIELD AND POOL, OR WILDCAT AXI APACHE - E. BLANCO
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 3, T-25N, R-4W
		12. COUNTY OR PARISH RIO ARRIBA
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) SET SURFACE CSG.	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 12 1/4" hole on 9-11-75. Set 8 5/8" K-55 24# csq. @ 222'. Cemented with 179 sks. Class "B" cement. Cement. circ. to stc. WOC 18 hrs. Tested csq. to 500 psi, held ok. Resumed drilling on 9-13-75.



SEP 20 1975

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE SR. ANALYST DATE 9-25-75

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

USGS-5 (Durango) L. P. PASO, Exxon. File