UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

5. LEASE	
SF 078884	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
Canyon Largo Unit	
8. FARM OR LEASE NAME	
Canyon Largo Unit	
9. WELL NO.	
281	
10. FIELD OR WILDCAT NAME So.Blanco Pictured Cliffs	
11. SEC., T., R., M., OR BLK. AND SURVEY OR	
AREA Sec. 15, T-25-N, R-6-W	
NMPM	
12. COUNTY OR PARISH 13. STATE	
Rio Arriba NM	
14. API NO.	

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil gas X other well well 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR PO Box 990, Farmington, NM 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1180'N, 1840'W AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)Current Status

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

El Paso Natural Gas completed this well at one time but it was non-productive. We have performed some remedial cement work and when road conditions permit we plan to reperforate and frac.

Set @ Subsurface Safety Valve: Manu. and Type ____ 18. I hereby certify that the foregoing is true and correct TITLE Drilling Clerk DATE -March 10, 1978

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

MAR 13 1978