

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. A2-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Contract No. 122

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Axi Apache "O"

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Axi Apache
S. Blanco - PC

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 10, T-25N, R-4W

12. COUNTY OR PARISH

Rio Arriba N.M.

13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

900' FSL + 1650' FWL of Sec. 10

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7320' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 6 3/4" hole from 520' to TD 3905' at 9:30 PM
6-2-77. Ran 123 joints 2 7/8" 6.5 LB, 8 Rd, J-55 casing.
Set at 3886'. Cmt. w/ 1600 gals. mud flush, 200 SKs light
weight, 2% CaCl₂, 1/2 #/sk floccle, .75% CFR-2. 70 SKs Class B
w/ 2% CaCl₂ w/ 1/4 #/sk floccle, .75% CFR-2. Plugged
down at 8:40 PM, 6-3-77. Waiting on completion
rig.

18. I hereby certify that the foregoing is true and correct

SIGNED

Wm. A. Butler

TITLE

Admin. Supr.

DATE

6-8-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

USGS - Durango (5), Gas Co. N.M. (2), Exxon, MJL, BEA, File