UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEFACIMENT OF THE INTERIOR	CONTYACT	10.42
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE	
	JICANI 115 1	4016 his
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NA	ME, y a
	# S & A	6 d. 6
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	္ ္ ႏုိင္ငံႏို
	AYI Anid	D_{ij}
1. oil gas well other	9. WELL NO.	φ <u> </u>
	5. WELL NO. 50 H	6 ,b
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NA	<u> </u>
Continents Oil Company	D. 11. 1 D. L.	
Box 460 Hobbs NM. 88240	Dallard FICTY	4rd 4/1745
	11. SEC., T., R., M., OR BL	K. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec 19 7-2	4"N" R" - W
below.) AT SURFACE: 2310' FNL + 990' FWL	12. COUNTY OR PARISH	13. STATES 3
AT TOP PROD. INTERVAL:	R. ARDIRA	A A
AT TOTAL DEPTH:	THO MINIOR FOR	7/4/8/3
AC OUTOK ADDOODDIATE DOY TO INDICATE MATURE OF MOTIOE	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	= - 1 	·
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6685	
TEST WATER SHUT-OFF \(\Pi \)	र १९५३ १९५३ १९५४	6 383 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
FRACTURE TREAT	200 200 200 200 200 200 200 200 200 200	90 2616 2616 2616 2616
SHOOT OR ACIDIZE		114 100 100 101 101 101
REPAIR WELL	(NOTE: Report results of mul-	ວ ຜູ້ = tiple completion or zone
PULL OR ALTER CASING 🔲 🔲	change on Form 9-33	30.) ₂
MULTIPLE COMPLETE		enoite enoite bades ream, rom
CHANGE ZONES	지 원활동	01160 71160 71160 71160 71160
(other) Sof 85% Surface C59,	를 고입하다.	hructi
(Ollier)	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	A COLUMN
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and a	give pertinent dates,
including estimated date of starting any proposed work. If well is d	irectionally drilled, give subs	urface locations and
measured and true vertical depths for all markers and zones pertinen		
Spudded 11-2-77 and Dilt	114 Hole	TO 575.
P' -12" 2= 4 h == 0		~
Ray 828" 324 K-55 Csg 50+	41 322,	MIU
U/ 310 SX Class B" CMT with	7% CACLZ	- , 1149
Down AT 3:15 AM 11-3-77.	Circ, Bock	100 5X
CMT, W.O.C. Tostod (59	10 1000 PS	1,4010
· · · · · · · · · · · · · · · · · · ·		돌린 환호뉴림
OK. Drld Afreed With 7 7/8" He	7/€, ağa∏a	
, , ,		
	동유통증요	
Subsurface Safety Valve: Manu. and Type	Set @	<u>ත් ද්රීම්</u> Ft.
outsurface outerly various manual and type	중요한화닭.	्रेड इ.स. १५५५ इ.स. १५५५
18. I hereby certify that the foregoing is true and correct	୍କୁ ପ୍ରତିଶ୍ୱର	सुड , ७,८ सि छ
SIGNED THE ADMINES	VP/ DATE 11-4-7	
	3%	
(This space for Federal or State of	ice use)	<u> </u>
APPROVED BY TITLE	DATE SERVICE	
APPROVED BY TITLE TOTALL CONDITIONS OF APPROVAL, IF ANY:	្តិ ខ្លួន គ្នាបា	TO BEN F
	5 t 2 EM	1
	No.	ล้มก บ อีซี สี 1977
1	· · ·	11 LJ T G 1911

USGS-5, G25 CO. N.M., EXXON, MTL, BEA, FILS. GEOLOGICAL SUR DUTINGO DURANGO, COLO.