

## SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other ☐

## 2. NAME OF OPERATOR

Continental a/c company

3. ADDRESS OF OPERATOR  
Box 460 Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1190 FSL & 1340 FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) Set 8 1/2" Surp

39 X

## 5. LEASE

Contract No. 147.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Ticarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

AX1 Apache J

9. WELL NO.

10. FIELD OR WILDCAT NAME

5. Blanco Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 7, T. 25N, R. 5W

12. COUNTY OR PARISH 13. STATE

Rio Arriba N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6694' BR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 1-30-78 and drilled 12 1/2" Hole to 510'.  
Set 8 1/2" 244 R-55 CSG AT 509'. CMTD W/300  
SX clings "B" CMT With Additives. W.O.C 18 Hrs  
and Tested to 500 PSI, Hold OK, Drild Ahead  
with 7 7/8" Hole.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Wm. G. Rutherford TITLE FORM. Supv. DATE 2-12-18

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**\*See Instructions on Reverse Side**

USGS(57), G-2 CO. N.M., EXRON, MJL, BEA, FILE