

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-02402	
2. NAME OF OPERATOR ARCO Oil & Gas Co., A Division of Atlantic Richfield Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME ---	
3. ADDRESS OF OPERATOR 1816 E. Mojave, Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME ---	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface (SW SE) 800'FSL & 1840'FEL Sec. 29		8. FARM OR LEASE NAME Chacon Federal	
14. PERMIT NO. 30-039-21583		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7125'GR 7139RKB		10. FIELD AND POOL, OR WILDCAT W. Lindrith-Gallup/Dakota	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29-24N-3W	
		12. COUNTY OR PARISH Rio Arriba	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) Bury Paraffin-Tank Bottoms ☒

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

ARCO Oil and Gas Company intends to remove a 300 bbl. oil tank from the indicated lease for installation on one of our Southern Ute leases. The tank selected to be moved contains approximately 7-8 inches of paraffin/tank bottoms. ARCO respectfully requests permission to bury this paraffin/tank bottoms on the well location prior to movement of the tank. The tank bottoms appears to be comprised of mostly paraffin, sand and B S & W which has solidified requiring it's removal by shoveling.

RECEIVED  
BLM MAIL ROOM

88 OCT 14 AM 8:19

FARMINGTON RESOURCE AREA  
FARMINGTON, NEW MEXICO

RECEIVED

DEC 30 1988

WATER DIV.

3

As per discussion between Dave Corzine and Bruce Kennedy, a total of only one barrel of paraffin/tank bottoms was present. Bruce gave verbal approval to bury the small volume on location.

18. I hereby certify that the foregoing is true and correct

SIGNED D.E. Corzine

TITLE Production Supervisor

DATE October 12, 1988

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE DEC 27 1988

APPROVED

James E. Edwards  
AREA MANAGER

NM000

\*See Instructions on Reverse Side