UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5. LEASE	
SF-080566	SE NAME
6. IF INDIAN, ALLOTTEE OR TRIE	SE NAME
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME	S :
- !	-
RUDDOCK	
9. WELL NO.	
9	3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
10. FIELD OR WILDCAT NAME	Superito
PICTURED CLIFF	
11. SEC., T., R., M., OR BLK. AN	SURVEY OR
AREA	
SEC. 2, T25N, R3W	
12. COUNTY OR PARISH 13. ST	IAIL
RIO ARRIBA NEW	MEXICO
14. API NO.	구 밝힌 항
T : : : : : : : : : : : : : : : : : : :	
15. ELEVATIONS (SHOW DF, KI	OR AND WD)
	JD, 11110 11-7
7374 GR	
	one of the second of the seco
	E 4 1

GEOLOGICAL SURVEI	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
eservoir, Use Form 9-331-C for such proposator,	RUDDOCK
1. oil gas x other	9. WELL NO.
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME Superito
PETRO-LEWIS CORPORATION	PICTURED CLIFF
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
P.O. BOX 509 - LEVELLAND, TEXAS 79336	AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	SEC. 2, T25N, R3W
below.) AT SURFACE: 900' FNL & 1750' FWL	12. COUNTY OR PARISH 13. STATE
AT SURFACE: 900 FILE & 1750 FILE AT TOP PROD. INTERVAL: 3958'	RIO ARRIBA NEW MEXICO
AT TOP PROD. INTERVAL. 3333 AT TOTAL DEPTH: 4100*	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	7374 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
KEQUEST FOR FILTREST	
TEST WATER SHUT-OFF U	그 그 그 그 그 그 중 한 경험을 하는 것 같아.
SHOOT OR ACIDIZE	the of multiple completion or zone
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING	
MULTIPLE COMPLETE	
CHANGE ZONES ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	ာ နှစ်ရှိဆို သို့ သို့သို့ မေ
(other) RUN & CMT. PRODUCTION CSG.	
	te all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work in the measured and true vertical depths for all markers and zones pertine	nt to this work.)*
	101 in the $5-1/2$ " $14%$
** FF AMIA AAAINA CITINU HU7.3 A	1.20 60200
1 /150 UALIABITEON II	OUL TOTTOMOG WILLS
Cemented w/150 sxs. Harribureon in Class "B" w/3% calcium chloride.	Good circulation Bumped
plug w/1500# psi.	
plug W/1300# psi:	
4-16-78 - 5:40 A.M Plug down. W.O.C. and move rig.	
W.O.C. and move rig.	MA
	Value of the same
	Set @ Ft
Subsurface Safety Valve: Manu. and Type	Set @
18. I hereby certify that the dregging is true and correct	
18. Thereby certify the state of the Sr. Drlg. For	oreman pare 5/4/78
SIGNED FILE OF SIGNED	
(This space for Federal or State	office use)
-	그 그 그 그 그 그 그 그 그 그 가 없는 그 그 가 없는 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그

____ TITLE _