

4-USGS (Durango) 1-Flag-Redfern 1-File

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SE 078562

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Largo Spur

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Ballard PC

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 18 T24N R6W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

NM

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Flag-Redfern Oil Co.

3. ADDRESS OF OPERATOR

Box 234, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

1580' FSL - 810' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6568' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) CSQ

SUBSEQUENT REPORT OF

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

7-22-78 TD 2135'. Conditioning hole to log.

7-23-78 Ran IES log by Welex.. Ran 72 jts 2-7/8" OD 6.4# CW-55 10R  
NEUE tbg for csg. TE 2125.64'. set @ 2125' GR. Had good circulation  
and reciprocated pipe while cementing. Cemented w/75 sx 65-35  
w/12% gel w/1/4# flo cele per sx followed by 50 sx class "B" neat  
w/1/4 # flo cele per sx. Total slurry 256 cu ft. Preflushed hole  
w/10 bbls CW-100 chemical wash. Bumped plug w/1500 psi. Released  
to 750 psi. Shut in. POB 7:15 p.m. 7-22-78.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Thomas A. Dugan*  
Thomas A. Dugan

TITLE

Agent

(This space for Federal or State Office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

U. S. GEOLOGICAL SURVEY  
DURANGO, CO.

DATE

RECEIVED  
JUL 27 1978

DATE

7-24-78