## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	Budget boiles no. 42 http://							
ĺ	5. LEASE							
	USA NM 23043							
1	6. IF INDIAN, ALLOTTEE OR TRIBE NAME							
-								
	7. UNIT AGREEMENT NAME							
	8. FARM OR LEASE NAME							
_	Schalk 43							
	9. WELL NO.							
	. 2							
10. FIELD OR WILDCAT NAME								
_	Wildcat							
	11. SEC., T., R., M., OR BLK. AND SURVEY OR							
_	AREA							
	Sec. 34, T-25N, R-3W							
	12. COUNTY OR PARISH 13. STATE							
	Rio Arriba New Mexico							
_	14. API NO.							
	<u> </u>							
	15. ELEVATIONS (SHOW DF, KDB, AND WD)							
	7213'							

SUNDRY N	OTICES AND F	REPORTS (	ON WELLS	7. UNIT AC	SKEEMENI NA	AME	-
(Do not use this form	for proposals to drill or 331—C for such proposals	to deepen or plu	g back to a different				<del></del>
reservoir. Use Form 9–	331-C for such proposals	-l					
1. oil g	as 🔀 other				lk 43		-
well 🗀 w	ell 🔼 other			9. WELL N	0.		
2. NAME OF OPE	2						
Schalk	10. FIELD OR WILDCAT NAME						
3. ADDRESS OF				Wild	cat		
P. O.	11. SEC., T., R., M., OR BLK. AND SURVEY OR						
4. LOCATION OF	AREA						
below.) 790		0'FEL		Sec. 34, T-25N, R-3W			
AT SURFACE:	•				Y OR PARISH		
AT TOP PROD				Rio Arr	iba	New	Mexico
AT TOTAL DEF	PTH:			14. API NO			
16. CHECK APPRO	PRIATE BOX TO IN	IDICATE NATI	JRE OF NOTICE,		-	`.	· :
REPORT, OR	OTHER DATA			15. ELEVAT	TONS (SHOW	DF, KDE	3, AND WD)
				7213'			•
REQUEST FOR AP	PROVAL TO:	SUBSEQUENT	REPORT OF:				
TEST WATER SHU	T-OFF □					·	• • •
FRACTURE TREAT						=	
SHOOT OR ACIDIZ	.Έ ∐					1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1200
REPAIR WELL		:	4		ort results of mi		digition on zone
PULL OR ALTER ( MULTIPLE COMPL		H		, , ,	/ / /		
CHANGE ZONES		1 1			1		4 % 7
ABANDON*				<u>\$</u>	1	1	Anna A
(other) Abando	on 👺	×				mi .	一代學的使
Zone					<del> </del>	$C \subset CO$	V COM
17. DESCRIBE PR	OPOSED OR COMPL nated date of starting	ETED OPERAT	TONS (Clearly stated work of wall is d	e all pertinen lirectionally dr	t details, and, illed give sub	give per	cinent dates,
measured and	true vertical depths	for all markers	and zones pertiner	nt to this work	.)*		
							P. V. Britannian St. Co.
8/8/80	Pulled 450	7' 2-3/8	" Tubing o	ut of we	211	-	- 3 -
8/9/80	Schlumberg	er pluq	back T.D.	was 4675	o'. Ran	÷	୍ଞ୍ର ଅ
0, 5, 00	dump bailer in well with eno			ugh cen	ment to		- 1
	fill 25' of hole, in $4-1/2$ " c					-	
	1111 25 0	1 11010,	<b>211</b>			=	
	New Plug b	ack TD	4650'				
	new rad b	dek I.D.	1000			<del>-</del>	
					· ·		. i.
						± 11	; <del>- '</del> -
						= =	
							_

Subsurface Safety Valve: Manu. and Type \_ 18. I hereby certify that the foregoing is true and correct Mittle Managing Partnerate

(This space for Federal or State office use)

\_ TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

DATE

AUG 22 1980

