

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-079456

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Chacon Hill

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Chacon-Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 20-24N-3W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR ARCO Oil and Gas Company, Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR

Suite 501, 1860 Lincoln St., Denver, Colo. 80295

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

790' FSL & 1850' FEL Section 20 (SW SE) (Unit O)

14. PERMIT NO.

API #30-039-22007

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6941' GL (Ungraded)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) N.O. Spud & Surf. Csg.

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud 12-1/4" hole @ 5:00 p.m., 5/4/79. Drilled to 315'. RU & ran 8 jts (309.85') 8-5/8" OD 24# K-55 ST&C casing set @ 306' RKB, cmtd w/250 sx Class "B" cmt w/2% CaCl₂ + 1/4# flocele/sx w/good returns. Guideshoe @ 306'. Plugged down @ 12:30 a.m., 5/5/79. Pressure tested blind rams and pipe rams to 1000#, OK.

Waiting on cement.



RECEIVED

MAY 14 1979

U. S. GEOLOGICAL SURVEY
ORANGO, COL.

18. I hereby certify that the foregoing is true and correct

SIGNED W. A. Walther, Jr.

TITLE Operations Manager

DATE 5/7/79.

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

State

*See Instructions on Reverse Side