## UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 03992
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	7. UNIT AGREEMENT NAME:
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT TYAMES
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	East Lindrith
1. oil gas well other	
2. NAME OF OPERATOR	9. WELL NO. 1 またい 1.000 1 1.0
J. Gregory Merrion & Robert L. Bayless	10. FIELD OR WILDCAT NAME 및 프로드
3. ADDRESS OF OPERATOR	Blanco South F 70 2 2
P.O. Box 507, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA THE SOLUTION AND AND AND AND AND AND AND AND AND AN
below.)	SEction 22, T24N, R2W 2 2
AT SURFACE: 1120' FNL & 790' FEL AT TOP PROD. INTERVAL: same	12. COUNTY OR PARISH 135 STATE
AT TOP PROD. INTERVAL: same AT TOTAL DEPTH: same	Rio Arriba (기계 M. M. 연호 경기 (기계 기계 기
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	무건물을 곧 심용되고
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	7240' GL \$ 7245' K.B.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	40.46
TEST WATER SHUT-OFF	ober Eur Huser Galla Price Calla Ca ca ca ca ca ca ca ca ca ca ca ca ca ca
RACTURE TREAT	gar billu 2 (ne v leso) sa leso) sa lauga di bluga di tous qot ot i
SHOOT OR ACIDIZE U U REPAIR WELL U	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [	change on Form 9–330.)를 물골꽃을 🤄
MULTIPLE COMPLETE	्र अनुष्ट के मेहिल्हा है।
CHANGE ZONES	igaala rogall rogalia baniab baniab raabiil raabiila raabiila raabiila raabiila raabiila
other) Surface Casing X	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and	
measured and true vertical depths for all markers and zones pertinen	t to this work.)* 불물을 표 그 글 글 글 글
10-13-79 Drilled 9-7/8" surface hole to 103	2! Pan 3 30ints (97!) 2 4 6 5
7", 20 #, K-55 casing. Set at 102	2' and cemented with 50 = 2 = 3
sacks cement 2% CACL2. Had cement	t returns to ground surface.
10-14-79 WOC 12 hours. BOP. Pressure test	ted surface casing and BOP; -
to 500 psi; ok.	
• ,	10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	Company of the control of the contro
	The part of the pa
	1 5 1979
C.1.1	4 × 1070
1 → ⊀	1 5 1979 Set @ Ft.
Subsurface Safety Valve( Manu. and Type	
18. I hereby certify that the foregoing is true and correct	변경 (18 명 전 18 명
\\ \h.	# November 13, 1979
SIGNED TITLE CO-OWNER	DATE NOVEMBER 43, 1273
(This space for Federal or State office use)	
APPROVED BY	Ce use)
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	
	art D to tropholy a tropholy a tropholy a tropholy tropholy tropholy tropholy archibroly
	·