PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

UNITED STATES DEPARTMENT OF THE INTE **GEOLOGICAL SURVEY**

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078908 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Lindrith Unit 8. FARM OR LEASE NAME
1. oil gas well other	Lindrith Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	96. 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico	S. Blanco P.C. 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1130'N, 1450'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 8, T-24-N, R-2-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PBTD 3453'. Tested casing to 4000#, OK. Perfed 3324,3330,3346,3352,3364, 9-7-79: 3377,3384' W/1 SPZ. Fraced w/46,000# 10/20 sand, 41,098 gal. slick water. Flushed w/840 gal. water.

Subsurface Safety Valve: Manu. and Type ___ 18. I hereby certify that the foregoing is true and correct TITLE Drilling Clerk DATE Sept. 10, 1979 SIGNED (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: