

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐  
well well  
2. NAME OF OPERATOR  
El Paso Natural Gas Company  
3. ADDRESS OF OPERATOR  
Box 289, Farmington, New Mexico 87401  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1165' S, 1450' W  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA


| REQUEST FOR APPROVAL TO: |                          | SUBSEQUENT REPORT OF:               |
|--------------------------|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF      | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| FRACTURE TREAT           | <input type="checkbox"/> | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE         | <input type="checkbox"/> | <input type="checkbox"/>            |
| REPAIR WELL              | <input type="checkbox"/> | <input type="checkbox"/>            |
| PULL OR ALTER CASING     | <input type="checkbox"/> | <input type="checkbox"/>            |
| MULTIPLE COMPLETE        | <input type="checkbox"/> | <input type="checkbox"/>            |
| CHANGE ZONES             | <input type="checkbox"/> | <input type="checkbox"/>            |
| ABANDON*                 | <input type="checkbox"/> | <input type="checkbox"/>            |
| (other)                  | <input type="checkbox"/> | <input type="checkbox"/>            |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-6-79: TD 3476'. Ran 108 joints 2 7/8", 6.4#, J-55 production casing, 3476' set at 3476'. Baffle set at 3464'. Cemented w/171 cu. ft. cement. WOC 18 hours. Top of cement at 2500'.

5. LEASE  
SF 078911  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
Lindrith Unit  
8. FARM OR LEASE NAME  
Lindrith Unit  
9. WELL NO.  
98  
10. FIELD OR WILDCAT NAME  
So. Blanco P.C.  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 3, T-24-N, R-3-W  
N.M.P.M.  
12. COUNTY OR PARISH  
Rio Arriba  
13. STATE  
New Mexico  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
7046' G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)



Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Drilling Clerk DATE August 14, 1979

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

AUG 16 1979

U. S. GEOLOGICAL SURVEY  
DURANGO, COLO.