UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

HAUTED CTATEC	
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Jicarilla Contract #111
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Jicarilla
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	Jicarilla
well X well other	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil and Gas Company	107
Division of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Suite 501 Lincoln Tower	W.Lindrith Gallup/Dakota
1860 Lincoln Street, Denver, Colorado 80295	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	7-24N-4W
AT SURFACE: 500' FNL & 450' FEL (NE NE)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Unit A	Rio Arriba New Mexico
AT TOTAL DEPTH: Approx. the same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-039-22092
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6750' GL 6764' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	CHOTE B
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON* N.O. spud and setting surface casing	
(other) N.O. Spud and Secting Surface casing	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. Spud 4:00 p.m. 8-27-79. Ran 8 jts 8-5/8", 24#, K-55, R 3, ST&C casing with GS and baffle plate (330') landed at 302' KB. Cemented with 300 sks Class "B", 2% CaCl. P.D. 1:00 a.m. 8-28-79. Circulated some good cement. Pressure tested blind rams and pipe rams to 1000#, held OK.

•		מוסונים	/
Subsurface Safety Valve: Manu. and TypeSo	et (. Ft

18. I hereby certify that the foregoing is true and correct

Operations

DATE .

Manager

(This space for Federal or State office use)

APPROVED BY __ CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY DURIANGO, COLO.