

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Mobil Producing Texas & New Mexico Inc.
3. ADDRESS OF OPERATOR
9 Greenway Plaza, Ste. 2700, Hou., TX 77046
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1739 FSL & 861 FWL
AT TOP PROD. INTERVAL: same as surface
AT TOTAL DEPTH: same as surface

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Spud & Surface csg. ☐

☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
Santa Fe 078914
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Lindrith B Unit
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
Chacon-Dakota Associated
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 28, T24N, R3W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
7001-GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/21/79 - Cactus Drilg. Co. spud 2 AM.

12/22/79 - TD 17-1/2" hole @ 480'. Ran 11 jts. 13-3/8" 48# H40 set @ 470'. Howco cmt. w/ 500 sx B + 2% CaCl₂ + 2/4# Flocele. Cmt. circ. to surface. PD 9AM NU tested to 1000 psi/OK.12/31/79 - TD reached 1:30 AM @ 3856. Circ. 3 hrs. Ran 36 jts. 14 1/2" 8-5/8" 32# K55 + 60 jts. 2418' 24# K55 w/ 2 cmt. baskets @ 1030' & @ 496'. Howco cmt. @ 3852 w/ 650 sxs. 1t. + 100 sxs. B + 2% CaCl₂. PD 5AM 1/1/80. Cmt. circ. to surface.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Ruthie Jay TITLE Authorized Agent DATE January 9, 1980

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

JAN 17 '80

*See Instructions on Reverse Side

JAN 11 1980

U. S. GEOLOGICAL SURVEY
D-1000, 1-1-80