5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	Jicarilla Apache 💆 🥏 🗕	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form 'or proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–31–C for such proposals.)	1 5 5 5 F F F F F	
reservoir. Use Form 9–331–C for such proposals.)	.1	_
1. oil gas 🕞	Jicarilla Apache Tribal 12	:5
well well well other	9. WELL NO. 94 18 19 19 19 19 19 19 19 19 19 19 19 19 19	
2. NAME OF OPERATOR		
Amoco Production Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Lindrith-Gallup-Dakota Wes	
501 Airport Drive Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVE	y or
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA STATE OF THE PARTY OF THE	
below.) AT SURFACE: 935' FWL & 1720'FSL Section 26,	NW/SW Section 26 T25N, R4W 12. COUNTY OR PARISH 13. STATE 5	
AT TOP PROD. INTERVAL: same T25N R4W	1 5 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
AT TOTAL DEFTH: Same	Rio Arriba New Mexic	<u></u>
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-039-22143	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND	WD
REPORT, ON STILL STATE	7206' GLF Z = 5	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	# 180 GE 27 6	
TEST WATER SHUT-OFF		
FRACTURE TREAT	4 1 H 2 1 B 3 K 2 B 3 K 3 B 3	
SHOOT OR ACIDIZE	- 1111 1 : 항상 14 1 (한 숙설처음	
REPAIR WELL UPPER CASING UPPER	(NOTE: Report results of multiple completion of change on Form 9–330.)	r zone
MULTIPLE COMPLETE		
CHANGE ZONES	보는 상한 사람들은 기를 기뻐되었다.	:
ABANDON*	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	ï
(other) Spud & Set Surface Casing	그	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	te all pertinent details, and give pertinent of directionally drilled, give subsurface locations	lates s and
measured and true vertical depths for all markers and zones pertinel	nt to this work.)* See See See See See See See See See Se	
Spudded well on 9-27-79. Drilled to 402	2' and set $8 = 5/8$ " $= 24.300$ $= 200$	d sı
face casing. Cemented surface casing with 31	15 sx class "B" Neat cement co	, onta
ing 2% CaCl ₂ . Circulated out 20 sx good ceme		
1116 270 04072.		_
Presently drilling 7-7/8 hole to TD.		
		,
	THE BEST OF THE STATE OF THE ST	
	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	-
	1 1990 - 1 천조님위원 시원 작업부립	:
	그는 그에게 기진통하실함 협상 방송행을	<u>-</u>
		i T
	្រាស់ ស្រីស្វាស្វាស្វាស់ ស្វាស់ ស	: Ft
Subsurface Safety Valve: Manu. and Type		
18. I hereby certify that the foregoing is true and correct	នៃក្រុម មេខា មេខា មេខា មេខា មេខា មេខា មេខា មេខ	
Original Signed By Dist Adm. St	upr 79 % \$ 3-	:
SIGNED E. E. SYOBODA TITLE	DATE	<u> </u>
(This space for Federal or State of	ffice use) မြည်တွင် စုံမြို့ ကြို့ရှိခဲ့	<u>.</u>
APPROVED BY	DATE	- :
APPROVED BY TITLE CONDITIONS OF API'ROVAL, IF ANY:		ī -
	골취용하는 경험 별했다.	į.
		ت
*See Instructions on Reverse	Side	