5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	Contract No. 10	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	Jicarilla Apache	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME	
reservoir, Use Form 9–331–C for such proposals.) 1. oil gas	8. FARM OR LEASE NAME Jicarilla "L"	
	9. WELL NO. 2 - E	
2. NAME OF OPERATOR		
Supron Energy Corporation	10. FIELD OR WILDCAT NAME Otero Gallup	
3. ADDRESS OF OPERATOR B. O. Barris 2022 Forming to a New Marriag 87/01	<u></u>	
P.O. Box 803, Farmington, New Mexico 87401	 SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T-24N, R-5W 	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	N.M.P.M.	
AT SURFACE: 860 Ft./N; 990 Ft./W line AT TOP PROD. INTERVAL: Same as above	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico	
AT TOTAL DEPTH: Same as above	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6658 R.K.B.	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
allogi ok Acibize	EIVED	
REPAIR WELL PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone 5 1 change on Form 9-330.)	
MULTIPLE COMPLETE	10 J 1 = 5 yr 0 and 1 and 1	
CHANGE ZONES	DOIGAL SURVEY	
ABANDON*	PMMGION, N. M.	
(other) Plugged Gallup Zone 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give pertinent dates	

- including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - 1. Perforated 12 shots in Gallup from 5857 to 5881 feet.
 - Treated with 1800 gal. 15% HCL. Foam fractured with 34,000 lb. of 20-40 sand and 2% KCL water.
 - Tests indicated the zone would not be commercially productive.
 - Set packer at 5521 feet R.K.B. and squeezed Gallup perforations with 150 sacks of class "B" with 2% calcium chloride.
 - Tested casing to 2500 P.S.I. Held OK.

	NEGETTE TO SUCCE.	
Subsurface Safety Valve: Manu. and Type	, ,	Set @Ft.
18. I hereby certify that the foregoing is t		
SIGNED Kenneth E. Roddy	TITLE Production Supt. DATE	June 20, 1980
	(This space for Federal or State office use)	A Second Property of the Second Property of t
APPROVED BY	TITLE DATE	<u> </u>