UNITED STATES

UNITED STATES	5. LEASE FROM A SECONDARY STATE OF THE SECONDARY SECONDA
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Fig. 6. 11 11 11 11 11 11 11 11 11 11 11 11 11
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	<u> 4555 9 455</u>
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
1. oil gas other	9. WELL NO. TOTAL A STATE
2. NAME OF OPERATOR ARCO Oil & Gas Company	116
Division of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME:
3. ADDRESS OF OPERATOR Suite 501	W. Lindrith - Gallup/Dakota
1860 Lincoln Street, Denver, Colorado 80295	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec 7-24N-4W 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
below.) AT SURFACE: 1980' FSL & 950' FEL (NE SE)	12. COUNTY OR PARISH 13. STATE 7 6
AT TOP PROD. INTERVAL: Unit I	Rio Arriba New Mexico
AT TOTAL DEPTH: Approx the same	14. API NO. 유통증별 글 등품증성
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-039-22161
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	67201-GIF - N FELE
TEST WATER SHUT-OFF	한 1 개 개 개 개 개 개 개 개 개 개 개 개 개 개 개 개 개 개
FRACTURE TREAT	ed bluce a duce
SHOOT OR ACIDIZE	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	change on Form 9-330.)
CHANGE ZONES	10 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
ABANDON*	1 - 교육 (1) 전 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
(other) N.O. Spud and set surface casing	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	te all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
measured and true vertical depths for all markers and zones pertines	
	하면 하는 사람들이 가는 사람들이 되었다.
MIRU. Spud 8:00 pm 11-21-79. Drilled to 305'	and ran 8 joints 8-5/8", a 🚆
24#, K-55, Rge. 3, ST&C casing (301.42') and land	ded @ 296' KB. Cemented with
300 sxs Class "B", 2% CaCl and 1/4# flocele/sx.	P D @ 11:15 am 11-22-79
with cement to surface. Pressure tested pipe a	nd blind rams to 1000# for
1 hour - held OK.	
·	
	1913
	Wo, or other sections of the section
	English Paragram
Culturations Cofety Volver Manus and Type	Set @Ft
Subsurface Safety Valve: Manu. and Type	361 @
18. I hereby certify that the foregoing is true and correct Operation	s Şulliya (14 dağı)
SIGNED WILL A THE Manager	DATE = 11-28-79
W. A. Walther, Jr. 7.1	
(This space for Federal or State of	mice use) 프로벌롱을 되는 얼음수요

Paul