

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐  
well well other

2. NAME OF OPERATOR

Mobil Producing TX. & N.M. Inc.

3. ADDRESS OF OPERATOR

9 Greenway Plaza, Ste. 2700, Houston, TX 77046

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1840 FNL &amp; 850 FWL

AT TOP PROD. INTERVAL: same as surface

AT TOTAL DEPTH: same as surface

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON\* ☐(other) Spud & set surface csg.CORRECTED REPORT

(NOTE: Report results of multiple completion or zone change on Form 9-330.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2/28/80 - Spud @ 4PM

2/29/80 - Ran 8 jts = 347' of 13-3/8" (H40 48# ST&amp;C csg.) set @ 318.

BJ cmt csg. w/350 x class B + 3% CaCl<sub>2</sub> + 1/4# FC/s. PD  
@ 7 AM. WOC 8 hrs. + NU. Tested csg. + BOP to 1000 psi/OK.

RECEIVED FOR RECORD



Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Robbie Jay TITLE Authorized Agent DATE March 28, 1980

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

\*See Instructions on Reverse Side

RECEIVED

MAR 31 1980

S. GEOLOGICAL SURVEY  
DURANGO, COLO.