| UNITED STATES | | | | | |
|----------------------------|--|--|--|--|--|
| DEPARTMENT OF THE INTERIOR | | | | | |
| GEOLOGICAL SURVEY | | | | | |

| 5-USGS (Farmington) 1-McHugh 1-File Dec. 1973 | Form Approved. Budget Bureau No. 42–R1424 | | |
|---|---|--|--|
| UNITED STATES DEPARTMENT OF THE INTERIOR | 5. LEASE NM 23032 | | |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.) | 7. UNIT AGREEMENT NAME | | |
| 1 all gas | 8. FARM OR LEASE NAME Federal | | |
| well well other 2. NAME OF OPERATOR | 9. WELL NO. 43- | | |
| Jerome IP. McHugh | 10. FIELD OR WILDCAT NAME | | |
| 3. ADDRESS OF OPERATOR Box 208, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) | | | |
| AT SURFACE: 1650' FSL - 790' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: | 12. COUNTY OR PARISH 13. STATE NM | | |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14. API NO. | | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 7285' GL | | |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SHOOT OR ACIDIZE SHOOT OR ACIDIZE | | | |
| REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE | (NOTE: Report results of multiple completion or zone change on Form 9–330.) | | |
| CHANGE ZONES | | | |
| (other) CSG 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state | e all pertinent details, and give pertinent dates, | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-4-80 TD 3460'

Laid down drill pipe. Ran 86 jts 4-1/2" OD 10.5# K-55.8R LT&C csg. TE 3484.15' set @ 3482' RKB. Reciprocated pipe and had good circulation while cementing. Preflushed hole w/10 bbls mud flush. Cemented w/75 sx 65-35 w/12% gel w/1/4# flo cele per sx followed by 125 sx class "B" neat w/12.5# gilsonite per sx. Total slurry 344 cu ft. Bumped plug w/1250 psi. Held OK. POB 3:20 a.m. Set slips and released rig @ 3:50 a.m. 3-5-80.

| Subsurface Safety Valve; Manu. and Type | | | Set @ Ft. |
|--|--|--------|-----------------------|
| 18. I hereby certify that the foregoing is | true and correct | | appared all |
| SIGNED Jim L. Jacobs | Agent | DATE _ | 5-9-80 |
| <i>S</i> ' | (This space for Federal or State office use) | | Treature the breaking |
| APPROVED BY | TITLE | _ DATE | [SAY 1 0 1980- |