

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR ARCO Oil and Gas Company
Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR
P. O. Box 5540, Denver, Colorado 80217

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1850' FEL & 2150' FSL (NW SE)
AT TOP PROD. INTERVAL: Unit J
AT TOTAL DEPTH: Approx the same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ ☐

FRACTURE TREAT ☐ ☐

SHOOT OR ACIDIZE ☐ ☐

REPAIR WELL ☐ ☐

PULL OR ALTER CASING ☐ ☐

MULTIPLE COMPLETE ☐ ☐

CHANGE ZONES ☐ ☐

ABANDON* ☐ ☐

(other) N.O. spud and set surface casing

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud 12-1/4" hole 4:00 pm 3-6-80 and drilled to 336'. Circ and ran 7 1/2" 8-5/8", K-55, 24#, ST&C casing and set shoe at 332.42' RKB with insert FC @ 286.16'. Cemented with 300 sxs Class "B" w/3% CaCl plus 1/4#sxs floccle. Plug did not bump. Had contaminated returns to the surface. Wait on cement 21 hrs. Ran 1" pipe 90' below GL down 8-5/8" annulus and pumped in 75 sxs Class "B" and 2% CaCl with complete returns throughout. Had cement returns to the surface. Job complete 10:45 pm 3-7-80. Pressure tested blind and pipe rams to 1000# for 30 mins - held OK.

Drilling ahead @1494' 3-8-80.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED W A Walther Jr TITLE Operations Manager DATE 3-13-80

W A Walther, Jr

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

5. LEASE
Jicarilla Contract #111

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla

9. WELL NO.
111

10. FIELD OR WILDCAT NAME
W.Lindrith Gallup/Dakota

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
5-24N 4W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.
30-039-22256

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6735' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

APPROVED FOR _____

MAR 25 '80

*See Instructions on Reverse Side

MAR 21 1980

DISTRICT
BY _____

U. S. GEOLOGICAL SURVEY
DENVER, COLO.