Maria de la compansa del compansa de la compansa del compansa de la compansa de l

UNITED STATES

	Budget Bureau	No. 42-R1
LEASE		

DEPARTMENT OF THE INTERIOR	SF 078907
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME Lindrith Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil gas gas	8. FARM OR LEASE NAME Lindrith Unit
well well other 2. NAME OF OPERATOR	9. WELL NO. 100
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME S. Blanco P.C.
P.O. Box 289, Farmington, NM 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 800'S, 900'E	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 6, T-24-N, R-
AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT	
PULL OR ALTER CASING	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is c	directionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertine 30: Spudded well. Drilled surface hole. J-55 surface casing 122 set at 136'. Circ. to surface. WOC 12 hours; held	nt to this work.)* Ran 3 joints 8 5/8", 24# Cemented w/ 206 cu. ft. cen
	007333
	Dial 3
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby contify that the foregoing is true and correct	
	lerk DATE October 8, 1980
(This space for Federal or State of	
APPROVED BY COURT OF APPROVAL IF HALVIII	DATE
CONDITIONS OF APPROVAE, IF MAN UILL	

*See Instructions on Reverse Side