7/

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

DEPARTMENT OF THE INTERIOR	SF 080565-A			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME			
1. oil gas WX other	Schalk-Gulf 9. WELL NO #3			
2. NAME OF OPERATOR JOHN E. SCHALK 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco Mesa Verde			
P. O. BOX 25825 / ALBUQ., NM 87125 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1120' FSL; 1520' FEL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 6, T-25N, R-3W			
AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7361' GR			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	The part with the part of the			
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) DRILLING X X	(NOTE: Report results of multiple completion or zone change on Form 9–330.)			

5. LEASE

AT TOTAL	DEPTH:		14. API NO.	į E	E # 55	
		NDICATE NATURE OF NOTICE,				
REPORT,	OR OTHER DATA		15. ELEVATIO			
	n Annoval TO	SUBSEQUENT REPORT OF:	7361	GR .	6.5% (* 	<u></u>
		SUBSEQUENT REPORT OF.		5 () £ ()		· ·
TEST WATER FRACTURE TE		H		무용목 보		<u>.</u>
SHOOT OR A		旨			그런 등리함	5
REPAIR WELL					Itiple completion	or zone
PULL OR ALT	TER CASING 🔲		chang	e on Form 9–3	30.는 글론말	
MULTIPLE CO						<u>.</u>
CHANGE ZON	IES 📙	片	Ī.	三 医囊肿的		
ABANDON* (other) DF	RILLING X	Х				· 5.
(other)				<u> </u>	* \$25	<u> </u>
17. DESCRIB	E PROPOSED OR COMPL	ETED OPERATIONS (Clearly state	e all pertinent	details, and	give pertinen	t dates,
including	estimated date of starting and true vertical depths	ng any proposed work. If well is d for all markers and zones pertiner	it to this work.)*	eu, give soo:	surface location)
measured				_		-
/3/80	Ran 151 join	ts (6326.10') 10.5#	4-1/2"	casing	set 0634)0' KBM.
	Cemented with	h 235 sacks H.L. wi	th 12.5#	Gilson	ite/sx.	_ Followed
	w/ 170 sxs c	lass <mark>'B',</mark> 50/50 Poz	: Mix wit	h 2% Ge	1, 6, 25	‡
		d 7# salt/sx.			트로 원원실	-
				3 8284	그림 독일하	
	The completion	on of the well is s	hceduled	for th	e latte:	r part
	of July, 1986	0, subject to rig a	vailabil	ity.		
	• .	-		85858	1000	200
				(출동 출 항된	ACUEP!	THE STATE OF THE S
		••				
					그림 첫 기울 종일	E
						,F986 i
			42 4 7		J Ě J Ē	êcan l
Subsurface S	afety Valve: Manu. and Ty	pe	· · · · · · · · · · · · · · · · · · ·		₩ *	FACT 186
18. Lhereby	certify that the foregoing i	s true and correct			ુ્મું ર મુંગ્યું છે	S. Agers.
	Y YOUNG	OPERATOR		7/8/8	الله المسلمة في المسلمة	The are the fire
SIGNED	MOPULAN.	THE OPERATOR	DATE	= =		5
1		(This space for Federal or State of	fice use)	= <u>5 5 5 5</u>		
			0.175	- 12 H 2 H 2 H 2 H 2 H 2 H 2 H 2 H 2 H 2		
APPROVED BY	OF APPROVAL, IF ANY:	TITLE	DATE			
CONDITIONS	or allowed in the				그림 불집	- [
				프랑함		1000
				4321	して こうしょご	1000

*See Instructions on Reverse Side