Form 9-331 Dec. 1973 Form Approved. Budget Bureau No. 42-R1424 Set LOL TE SELL STATES CASE TELL TO THE TELL THE 5. LEASE DEPARTMENT OF THE INTERIOR Contract 145 GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache 7. UNIT AGREEMENT NAME. SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drilf or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME 70. 3 Jicarilla "K" other well well 9. WELL NO. 2. NAME OF OPERATOR Southern Union Exploration Co. 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR Dallas, TX 75202 Basin Dakota 🦮 1212 Main St, Tx Federal Bldg, Suite 400 11. SEC., T., R., M., OR BLK. AND SURVEY OR 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AREA 5-67 Sec 1, \$\frac{1}{5}N, R5W AT SURFACE: 1095' FNL & 790' FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: Rio Arriba New Mexico AT TOTAL DEPTH: 14 API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6716' GR ′≦ ઈ REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: to qot TEST WATER SHUT-OFF FRACTURE TREAT 10 to 50 SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multip PULL OR ALTER CASING change on Form 9-MULTIPLE COMPLETE ni blund**a t**ns leatab (theen) b bodten) bu budt blue be CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up completion unit, drill out cement and DV tools, ran CCE, CBL, GR. (1 SPF). 4/12/81 Acidized with 2000 gallons 15% HCl. 4/14/81 Fracked with 71000 gelled water with 120,000# sand, flowed and swab tested.

4/11/81 Perforated Dakota from 7520' to 7541', 7553' to 7555' and 7559 to 7575'

4/17/81 Set CIBP at 7450'.

4/18/81 Perforated additional Dakota as follows: 7385-7394, 7396-7404, 7414-7421, and 7428'(1 SPF).

4/22/81 Acidized with 1500 gallons of 15% HCl.

4/23/81 Fracked with 52,836 gallons of gelled water with 88,000# of sand, flow and swab tested.

4/28/81 Removed BP and swab tested entire Dakota.

(OVER) = 1 Set @

18. I hereby certify that the foregoing is true and correct

Subsurface Safety Valve: Manu. and Type _

TITLE Drlg & Prod Engineer

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

DATE

*See Instructions on Reverse Side

ARMINGTON DISTRICA

18/8/9

and and and and