Form 9-331 Dec. 1973

UNITED STATES DEPARTMENT OF THE INTERIOR

	Form Approved. Budget Bureau No. 42-R1424
	5. LEASE
	SF-078874
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
_	
	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
	Canyon Largo Unit
	9. WELL NO. 11 11 11 11 11 11 11 11 11 11 11 11 11
	301 ਝਿਲਵੀ ਏ ਹੁੰਸ਼ੀਰ
	10. FIELD OR WILDCAT NAME ₩ = ₽ ₽ ₽
_	Devils Fork Gallup
	11. SEC., T., R., M., OR BLK. AND SURVEY OR
	AREA 具有型型 A 具是型量
	Section 4, T24N, R6W
	12. COUNTY OR PARISH 13. STATE
Ì	Rio Arriba New Mexico
	14. API NO.

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE/NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil 😡 gas 🗍	Canyon Largo Unit 5
well 🖾 well other	9. WELL NO.
2. NAME OF OPERATOR	301 ਝਿਸਲੇਹ ਹੈ ਹੈੜੋਵੇਂ
J. Gregory Merrion & Robert L. Bayless	10. FIELD OR WILDCAT NAME # = 2 }
3. ADDRESS OF OPERATOR	Devils Fork Gallup
P.O. Box 507 Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA STATE OF THE
below.)	Section 4, T24N, R6W
AT SURFACE: 790 FSL & 990 FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: same	Rio Arriba New Mexico
AT TOTAL DEPTH: same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6470 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	U470 GL
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zerie
MULTIPLE COMPLETE	
CHANGE ZONES	1 0000 0 10
ABANDON*	APR 2.7 19
(other) Cementing X	VOIL CON. CO
17 DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Clearly state	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e an pertinent details, and give pertinent dates, rectionally drilled, give subsurfact locations and
measured and true vertical depths for all markers and zones pertinent	t to this work)*

Supplemental to our Sundry Notice dated 04-13-81,

1st Stage Cement Job; cemented with 175 sacks Class H cement 2% gel (233 cubic ft. slurry). Calculated cement top 4697. No temperature survey run.

2nd Stage - Stage collar @ 4563. Cemented with 550 sacks Class B followed by 100 sacks Class H 2% gel (slurry volume = 1266 cubic ft.) Volume theoretically enough to circulate 226 cubic ft. to surface. Did not circulate cement. Did not run temperature survey. Had good circulation of mud through-out job.

Subsurface Safety Valve: Manu. and Ty	ype			Seti@			Ft.
18. I hereby certify that the pregoing SIGNED William William	is true and correct	Co-Owner	DATE		1981	१८६ - जार अवस्य भ्रम १९७ - दश्रि १९७ - दश्रि	
		Federal or State office use)		en e	2 3		_
PROVED BY TITLE NDITIONS OF APPROVAL, IF ANY:			DATE	. <u>* 1986</u> ;	<u> </u>	274 8151	
	MG	G)			TOT	EGORD	

*See Instructions on Reverse Side

FARMINGTON DISTRICT