orm	9-331
Dec.	1973

6 MMS, Fmn 1 So Union Ex

· _ 0 231	6 MMS, Fmn 1 So	Union Ex	1 File		Approv ed. Bureau No. 42-R1	1424
Form 9-331 6 MMS, Fmn 1 50 OITTOIL EX Dec. 1973 UNITED STATES			5. LEASE	: 5 : 3 : 3 : 3 : 3 : 3 : 3 : 3 : 3 : 3	0 644	
	DEPARTMENT OF THE INTERI	OR _	NM 25	426 11 50	<u> </u>	
GEOLOGICAL SURVEY		6. IF INDI	AN, ALLOTTEE (OR TRIBE NAME		
	AND DEPORTS	ON WELLS	7. UNIT A	GREEMENT NA		
_	NOTICES AND REPORTS form for proposals to drill or to deepen or p	alug back to a different		OD LEACE MAN	<u>명 등록</u> e 의 보위는	
(Do not use this reservoir, Use Fo	1111 9=331 °C 101 °C 1			or LEASE NAM can Hat를	E sainte	
1. oil well	gas Other P&	A .	9. WELL	NO. 1911	a bet dann ante	
2. NAME OF DL	OPERATOR JGAN PRODUCTION CORP.			or WILDCAT N	AME THE	
3. ADDRESS	of OPERATOR O Box 208, Farmington, N		11. SEC.,	T., R., M., OR B	LK. AND SURVE	Y OR
A LOCATIO	N OF WELL (REPORT LOCATION CLEA	ARLY. See space 17	AREA	6 T24N R7	e April	
below.)	1520' FSI - 1700'	FEL		TY OR PARISH		
AT SURF	PROD. INTERVAL:			Arriba عَامِهُ Arriba	S NMT I	
AT TOTA	L DEPTH:	ATURE OF NOTICE	14. API N	o. o. or	nsl Himidu	ī
16. CHECK A	APPROPRIATE BOX TO INDICATE N., OR OTHER DATA	ATORE OF HONOE,		ATIONS (SHOW		O WD)
REQUEST FO	OR APPROVAL TO: SUBSEQUE	NT REPORT OF:		in about		
TEST WATER	R SHUT-OFF 및 남			dota nach gota	15hu 1503 1503 1503	} ₹
FRACTURE SHOOT OR	ACIDIZE		MOTE: F	Report results of m	uittible completion	orzone
REPAIR WEL	ᅟᆸᅟᅟᆸ]	(NOTE: F	hange on Form 9	-330.) <u>-</u> = -	
PULL OR AI MULTIPLE (LTER CASING L	j			- 4354 - 3551	enediaan Treeliaan
CHANGE ZO	DNES D) }		E = 29-2		5 3
ABANDON* (other)		^		7 10 10 10 10 10 10 10 10 10 10 10 10 10	5 2 2	
17 DESCR	IBE PROPOSED OR COMPLETED OPEng estimated date of starting any prop	RATIONS (Clearly sta	te all pertin directionally	ent details, and drilled, give su	d give pertinent bsurface location	dates, ons and
includit measu	ng estimated date of starting any prop red and true vertical depths for all mar	kers and zones pertine	ent to this wo	ork.)* Didu Didu Didu Didu	1 ng	<u>.</u>
	•	•		동무구루의	· > 2 중국	<u>0</u> 112
	Rehabilitation of aband	oned well compl	eted as	TOTIONS: 9 5	in Janeite of the collection o	ည ဥ
	1. Erected a dry hole	marker - 5 sx c	cement pl	ug to sunf	ace = ====	
	2 Ruried mud left on	location.		6 7 3 4 5		io
	3. Ripped location, wa	ter barred the	access r	road, tander	eseeded = -	.
	both with seed mix Closed entrance to	#4. the access road	d with ar	earthen b	arrier whe	re it
	branches off the ac	cess to the Gra	and Gulch	n #1.595g		
	P+A 10-8-80			30 d 7		- :
. •	P417 10 0 00	•		200		. 3 . 5
		•		(A)		
Subsurfac	ce Safety Valve: Manu. and Type				et @	Ft.
19 1 here	aby certify that the foregoing is true and	correct		6-12-13-13-13-13-13-13-13-13-13-13-13-13-13-		1 - 1 1 - 1 1 - 7
18. 1 110	Sherman Elinanz	gRe Agent	D/	ATE)-82	: :
SIGNED		space for Federal or State				= =
	D BY	TITLE		DATE		
APPROVEC	INS OF APPROVAL IF ANY:			٠ ن ن ت		- - - - -
				9 3 5 5 ≈ 2	i. . A la	