

FIELD PIT SITE ASSESSMENT FORM

EL PASO FIELD SERVICES

GENERAL

93-450 SK 8/10/94
 Meter: ~~03-887~~ Location: Jelly Dog Jerry #1
 Operator #: 5954 Operator Name: J.P. McHugh P/L District: Ojito
 Coordinates: Letter: F Section 33 Township: 24 Range: 2
 Or Latitude _____ Longitude _____
 Pit Type: Dehydrator _____ Location Drip: X Line Drip: _____ Other: _____
 Site Assessment Date: 8/18/94 Area: 08 Run: 52

SITE ASSESSMENT

NMOCD Zone:

(From NMOCD
Maps)

Inside

☒ (1)

Outside

☐ (2)

Land Type:

BLM ☐ (1)

State ☐ (2)

Fee ☒ (3)

Dennis E. Fort
 DEPUTY OIL & GAS INSPECTOR

SEP 11 0 1996

Depth to Groundwater

Less Than 50 Feet (20 points)

☒ (1)

50 Ft to 99 Ft (10 points)

☐ (2)

Greater Than 100 Ft (0 points)

☐ (3)

Wellhead Protection Area :

Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points)

Horizontal Distance to Surface Water Body

Less Than 200 Ft (20 points)

☒ (1)

200 Ft to 1000 Ft (10 points)

☐ (2)

Greater Than 1000 Ft (0 points)

☐ (3)

Name of Surface Water Body Cañada Largo

(Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds)

Distance to Nearest Ephemeral Stream ☐ (1) < 100' (Navajo Pits Only)

☐ (2) > 100'

TOTAL HAZARD RANKING SCORE: 40 POINTS

REMARKS


Remarks : Redline Book - Not given Vulnerable Zone Type - Inside
One pit, pit is dry, will close one pit.

DIG 4 HAUL

ORIGINAL PIT LOCATION

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 37° Footage from Wellhead 94'
b) Length : 26' Width : 24' Depth : 3'



REMARKS

Remarks :

Pictures @ 1339 (13-16, Roll I)

Dump Truck

Pit is behind a locked gate. Well is abandoned.

Completed By:

Luca Rolley
Signature

8/8/94
Date

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL

Meter: 93450 Location: Jelly Dog Jerry #1
 Coordinates: Letter: F Section 33 Township: 24 Range: 2
 Or Latitude _____ Longitude _____
 Date Started : 10-24-94 Area: 08 Run: 52

FIELD OBSERVATIONS

Sample Number(s): KP 329
 Sample Depth: 12' Feet *10/2/94 as copied from sample log*
 Final PID Reading _____ PID Reading Depth 12' Feet
 Yes No
 Groundwater Encountered ☐ (1) ☒ (2) Approximate Depth _____ Feet

CLOSURE

Remediation Method :
 Excavation ☐ (1) Approx. Cubic Yards _____
 Onsite Bioremediation ☐ (2)
 Backfill Pit Without Excavation ☒ (3)
 Soil Disposition:
 Envirotech ☐ (1) ☐ (3) Tierra
 Other Facility ☐ (2) Name: _____
 Pit Closure Date: 10-24-94 Pit Closed By: B. E. I.

REMARKS

Remarks : Some Lid markers Pit looked clean
Pit now closed Pit

Signature of Specialist: [Signature]

Continental Gas Company

**FIELD SERVICES LABORATORY
ANALYTICAL REPORT**

PIT CLOSURE PROJECT - Soil Samples Inside the GWV Zone

SAMPLE IDENTIFICATION

SAMPLE NUMBER:

MTR CODE | SITE NAME:

SAMPLE DATE | TIME (Hrs):

SAMPLED BY:

DATE OF TPH EXT. | ANAL.:

DATE OF BTEX EXT. | ANAL.:

TYPE | DESCRIPTION:

Field ID

Lab ID

KP 329	946446
93450	N/A
10-24-94	245
N/A	
10-28-94	10-28-94
11-1-94	11-2-94
VG	light Brown Sand

REMARKS:

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE	<0.025	MG/KG	1			
TOLUENE	<0.025	MG/KG	1			
ETHYL BENZENE	<0.025	MG/KG	1			
TOTAL XYLENES	<0.025	MG/KG	1			
TOTAL BTEX	<0.10	MG/KG				
TPH (418.1)	24.7	MG/KG			2.05	28
HEADSPACE PID	1	PPM				
PERCENT SOLIDS	98.0	%				

-- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 --

The Surrogate Recovery was at 99 % for this sample All QA/QC was acceptable.
Narrative:

ATI Results attached.

DF = Dilution Factor Used

Date:

11/17/94



Analytical **Technologies, Inc.**

2709-D Pan American Freeway, NE Albuquerque, NM 87107
Phone (505) 344-3777 FAX (505) 344-4413

ATI I.D. **411303**

November 10, 1994

El Paso Natural Gas Co.
P.O. Box 4990
Farmington, NM 87499

Project Name/Number: PIT CLOSURE 24324

Attention: John Lambdin

On 11/01/94, Analytical Technologies, Inc., (ADHS License No. AZ0015), received a request to analyze **non-aqueous** samples. The samples were analyzed with EPA methodology or equivalent methods. The results of these analyses and the quality control data, which follow each set of analyses, are enclosed.


If you have any questions or comments, please do not hesitate to contact us at (505) 344-3777.

Letitia Krakowski, Ph.D.
Project Manager

H. Mitchell Rubenstein, Ph.D.
Laboratory Manager

MR:jt

Enclosure





Analytical Technologies, Inc.

GAS CHROMATOGRAPHY RESULTS

TEST : BTEX (EPA 8020)
CLIENT : EL PASO NATURAL GAS CO. ATI I.D.: 411303
PROJECT # : 24324
PROJECT NAME : PIT CLOSURE

SAMPLE ID. #	CLIENT I.D.	MATRIX	DATE SAMPLED	DATE EXTRACTED	DATE ANALYZED	DIL. FACTOR
01	946444	NON-AQ	10/24/94	11/01/94	11/02/94	1
02	946445	NON-AQ	10/24/94	11/01/94	11/02/94	1
03	946446	NON-AQ	10/24/94	11/01/94	11/02/94	1
PARAMETER			UNITS	01	02	03
BENZENE			MG/KG	<0.025	<0.025	<0.025
TOLUENE			MG/KG	<0.025	<0.025	<0.025
ETHYLBENZENE			MG/KG	<0.025	<0.025	<0.025
TOTAL XYLENES			MG/KG	<0.025	<0.025	<0.025

SURROGATE:

BROMOFLUOROBENZENE (%) 93 97 99