## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5. LEASE		
Santa	Fe <del>07891</del> 3	078914

								_		
6	1F	INDI	ΔN	AI1	OT	ΓFF	UB.	TRIRE	NΔ	MF

	OTICES AND REPORTS Of to proposals to drill or to deepen or plug		7. UNIT AGREEME Lindrith B		
reservoir. Use Form 9-	331-C for such proposals.)	8. FARM OR LEASE NAME			
2. NAME OF OPE	ell U other	·	9. WELL NO.		
Mobil Produ  3. ADDRESS OF  9 Greenway  4. LOCATION OF  below.)  AT SURFACE:	operator Hore Plaza Suite 2700  WELL (REPORT LOCATION CLEARLY  1840 CNL & 855 FWL INTERVAL: Same as surface		10. FIELD OR WILD Chacon-Dak 11. SEC., T., R., M., AREA Sec. 27, T2 12. COUNTY OR PA Rio Arriba 14. API NO.	ota Assoc. OR BLK. AND SURVEY OR	
16. CHECK APPROREPORT, OR (	PRIATE BOX TO INDICATE NATU	RE OF NOTICE,		SHOW DF, KDB, AND WD)	
REQUEST FOR AP TEST WATER SHU FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL PULL OR ALTER ( MULTIPLE COMPLI CHANGE ZONES ABANDON*	T-OFF	REPORT OF:		<b>s of multiple</b> completion or zone or <b>m 9–</b> 330.)	
including estin	OPOSED OR COMPLETED OPERATION nated date of starting any proposed true vertical depths for all markers and Broke down Dakota perf	work. If well is di and zones pertinen	rectionally drilled, given to this work.)*	ve subsurface locations and	
	SWF perfs w/ 50,000 ga	1 + 100,000#	20/40 sd.	AGR 23 1801 On alla Com- DIST. 3	
Subsurface Safety	Valve: Manu. and Type			Set @ Ft.	
18. I hereby certify	y that the foregoing is true and correc				
SIGNED TO	TITLE AL			-81	
	•	r Federal or State off	ice use)		
APPROVED BY CONDITIONS OF AP	PROVAL, IF ANY:		DATE	OVERTED FOR RECORD	
			•		

APR 27 1981