

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR Elliott Oil Company
3. ADDRESS OF OPERATOR Box 1355
Roswell, N.M. 88201
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1520'FNL & 790'FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

SEP 29 1981

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion operations change on Form 9-330.)

5. LEASE SF-080536
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Ora
9. WELL NO. #1
10. FIELD OR WILDCAT NAME Ojito Gallup/Blanco MesaVerde
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-T25N-R3W
12. COUNTY OR PARISH Rio Arriba
13. STATE N.M.
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) 7394'KB



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-26-81 SPUD 9:30 pm. Drilled 12½" hole to 270'. Ran 9 jts 9-5/8" 32.3# csg to 270' w/140 sx 2% CaCl. Cement circulated. WOC 12 hrs. Pressure tested to 500 psi. Held OK.

2-10-81 TD 6243. Ran 158 jts 7", 23 & 26# K-55 csg to 6238 w/200 sx. Cement circulated. DV tool at 3900. 2nd stage cemented w/400 sx Howcolite w/12½# gilsonite. Cement circulated. Pressure tested 3000 psi. Held OK.

2-14-81 Gas drilled to 8289. Ran 4½" liner to 8286 w/350 sx. Cement circulated. Pressure tested 3000#...test ok.

Subsurface Safety Valve: Manu. and Type n/a Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Curtis J. Little TITLE Agent DATE 3-2-81

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

Nmocc

SEP 2 1981

*See Instructions on Reverse Side

BY Smm