

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well

2. NAME OF OPERATOR  
CHACE OIL COMPANY, INC.

3. ADDRESS OF OPERATOR  
313 Washington SE Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "I" 1935' SL and 675' EL  
AT SURFACE:  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

Progress Report


X

RECEIVED

(NOTE: Report results of multiple operations to change on Form 9-330.)

NOV 09 1981

U.S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.



5. LEASE  
Jicarilla 70  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Jicarilla Apache  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Jicarilla 70  
9. WELL NO.  
14  
10. FIELD OR WILDCAT NAME  
South Lindrith Gallup Dakota  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 33, T24N, R4W  
12. COUNTY OR PARISH  
Rio Arriba  
13. STATE  
New Mexico  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
7040' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10/27/81 Drilling at 3575'. MW 9.1 Vis. 42 WL 4.5 Oil 8%  
10/28/81 Drilling at 4135'. MW 9.0 Vis. 35 WL 6.0 Oil 10%  
Bit #5 tripped at 3971'.  
10/29/81 Drilling at 4805'. MW 9.1 Vis. 36 WL 5.6 Oil 8%  
10/30/81 Drilling at 5173'. MW 9.0 Vis. 40 WL 6.0 Oil 5%  
Tripped Bit #6 at 5145'. Extra trip for cone.  
10/31/81 Drilling at 5824'. MW 9.2 Vis. 40 WL 5.0 Oil 3% Bit #6  
11/01/81 Drilling at 6393'. MW 9.0 Vis. 39 WL 4.2 Oil 8% 1% LCM  
11/02/81 Drilling at 6615'. MW 9.2 Vis. 39 WL 5.5 Oil 4% Bit #7  
Tripped Bit #6 at 6531'.  
11/03/81 Drilling at 6945'. MW 9.1 Vis. 40 WL 4.5 Oil 8%  
11/04/81 Drilling at 7207'. MW 9.1 Vis. 36 WL 6.0 Oil 4% Bit #8  
Tripped for bit at 7064'. (see next page)

Subsurface Safety Valve: Manu. and type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Royce McCarty TITLE President DATE 11/06/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

NMOCC