UNITED STATES

| THE PARTY OF THE INTERIOR | 7: | | | | |
|--|--|--|--|--|--|
| DEPARTMENT OF THE INTERIOR | Jicarilla 70 | | | | |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | | | | |
| | | | | | |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME | | | | |
| (Do not use this form for proposals to drill or to deepen or plug back to a diffe. | ent | | | | |
| (Do not use this form for proposals to drill or to deepen or plug back to a differeservoir. Use Form 9–331–C for such proposals.) | | | | | |
| 1 -11 | Jicarilla 70 | | | | |
| 1. oil y gas well other | 9. WELL NO. | | | | |
| 2. NAME OF OPERATOR | 11 | | | | |
| | 10. FIELD OR WILDCAT NAME | | | | |
| CHACE OIL COMPANY, INC. | So. Lindreth - Gallup-Dakota | | | | |
| 3. ADDRESS OF OPERATOR | 11 OFO T D II OD DIN AND SUDVEY OF | | | | |
| 313 Washington, S.E. Albug. NM 871 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space | AREA | | | | |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space | 17 Sec. 34, T24N, R4W | | | | |
| below.) Unit "K" 1850' WL & 1850' SL AT SURFACE: | 12. COUNTY OR PARISH 13. STATE | | | | |
| | Rio Arriba New Mexico | | | | |
| AT TOP PROD. INTERVAL: AT TOTAL DEPTH: | | | | | |
| | 14. API NO. | | | | |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTI | CE, 30-039-22820 | | | | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) | | | | |
| CURCIONIT DEPORT OF | 7042 GR | | | | |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | #일=용 : 1 일 4 월 호 | | | | |
| TEST WATER SHUT-OFF | | | | | |
| FRACTURE TREAT | Same and American | | | | |
| SHOOT OR ACIDIZE | (NOTE: Report results of multiple completion or zone | | | | |
| PULL OR ALTER CASING (5) | change on Form 9-330.) | | | | |
| MULTIPLE COMPLETE | | | | | |
| CHANGE ZONES | | | | | |
| ABANDON* D. 14-00-0 | PANTUAL SURVEY! Elylu F Allin F | | | | |
| (other) Delivery X FARELY | KATON, N. M. LINE DE LES PORTES DE LA CONTRACTOR DE LA CO | | | | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly including estimated date of starting any proposed work. If well measured and true vertical depths for all markers and zones per 2/6/82 Hook up gas. First deliver | tinent to this work.)* | | | | |
| Subsurface Safety Valve: Manu. and Type | Set @ Ft. | | | | |
| 18. I hereby certify that the foregoing is true and correct | | | | | |
| SIGNED THE Preside | nt DATE 2/8/82 - : | | | | |
| (This space for Federal or St | ate office use) | | | | |
| (IIIIS SPACE IN FEDERAL OF SE | | | | | |
| APPROVED BY TITLE | DATE FER 1 2 1982. | | | | |
| CONDITIONS OF APPROVAL, IF ANY: | | | | | |
| Aittean | The second secon | | | | |
| NMOCC | # EVENTHER IN THE FIRST | | | | |
| | BÝ | | | | |

| Form 9-331 | | | | | | | В | udget Bureau No | . 42-R1424 |
|------------------------------------|---|---|--------------------------------------|---|--|--|--|------------------|-----------------|
| Dec. 1973 | UN | NITED STA | TÉS | | | 5. LEASE | • | | |
| | DEPARTME | | | HOR. | | Jicari | lla 70 | | |
| | | OGICAL | ALL | MEN | | 6. IF IND | IAN, ALLOT | TEE OR TRIBE | NAME |
| | GEUL | .UGICAL S | | | 1 | Jicari | lla Apac | he | _ |
| | | | | CA ARROYNIA | A I | 7. UNIT | AGREEMEN' | T NAME 🥆 | |
| SUNDRY | NOTICES | ANUK | PLAKI | S1 1982W | adifferent | | | | |
| (Do not use this reservoir, Use Fo | form for proposa rm 9-331-C for s | is to drill or to | di CO | V. COM. | 1 | | OR LEASE! | NAME | |
| | | | DIS | 7.3 | | _Jicari | | | |
| 1. oil 🔀 | gas well | other | D. C | | | 9. WELL | | | |
| 2. NAME OF | | | - | A PROPERTY OF THE PARTY OF THE | | | 11 | | |
| 2. NAME OF | L COMPANY | . INC. | | | | | OR WILDC | | antro to |
| CHACE OF | OF OPERATO |)R | | | | South | Lindritt | Gallup D | CLIDVEY OR |
| and that | sington SF | Albugu | erque, | NM 871 | _08 | 11. SEC., | | OR BLK. AND | SURVETOR |
| 1 LOCATIO | N OF WELL (R | EPORT LOC | ATION CL | EARLY. See | space 17 | | 4, T24N, | R4W | |
| below.) | Unit "K" | 1850' V | NL and | 1850' SI | | | | ISH 13. STA | TE |
| AT SURF. | ACE: | | | | | Rio Ar | | New 1 | Mexico |
| AT TOP | PROD. INTER | √AL: | | | | 14. API I | | | |
| AT TOTAL | L DEPTH: | | | NATURE O | E NOTICE | 14. /// | 10. | | |
| 16. CHECK A | APPROPRIATE | BOX TO IT | NDICATE | NATURE O | r NOTICE, | 15 FLEV | ATIONS (S | HOW DF, KDE | 3, AND WD) |
| REPORT, | OR OTHER ! | JATA | | | | 7042' | GR | | |
| DEQUEST SO | R APPROVAL | TO: | SUBSEQU | JENT REPO | مسر: RT OF | | | | |
| TEST WATER | | | [| - Action | | | | | |
| FRACTURE T | REAT | Ō | بأسيه | | | · \ | \ | | |
| SHOOT OR | ACIDIZE | | Ţ. | · · · · · · · · · · · · · · · · | ST ST ST | NOTE: | Report results | of multiple com | pletion or zone |
| REPAIR WEL | .L | 님 | į | | | | change on Fo | rm 9–330.) | |
| PULL OR AL | TER CASING | H | / | [L | Vedenis | 500 | ļ | - | |
| MULTIPLE C CHANGE ZO | | Ħ | | abla | | (| • • | | |
| ABANDON* | | Ō. | | | Maria Cara Cara Cara Cara Cara Cara Cara | sure and a second | | | |
| (other) | | s Report | | <u> </u> | | | | | |
| 17. DESCRI includin measure | BE PROPOSED ig estimated da ed and true ver | OR COMP ate of starti rtical depths | LETED OP ng any pro for all ma | ERATIONS oposed work arkers and z | (Clearly stake). If well is ones pertine | te all perti directionally ent to this w | ork.)* | | ocations and |
| 10/12/ | /01 Dril | ling at | 1891 ' | Bit #2 | MW 9.3 | Vis. 4 | | | |
| 10/12/ | | ling at | 3091' | Rit #4 | MW 9.0 | V15. 3 | 2 WL 4. | | |
| 10/13/ | | ling at | 3205 | MW 9.0 | Vis. 42 | 2 WL 5. | 5 Oil 2 | 20% | |
| 10/14/ 10/15/ | /01 Dril | ling at | 3719' | MW 8.8 | Vis. 30 | 6 WL 5. | 5 Bit i | l ! 5 | |
| 10/13/ | 100 | bbls muc | after | trip at | 3567 | | | _ | |
| 10/16 | | ling at | 4305' | Ui+ 11h | MW 917 | Vis. 35 | WL 5.0 |) | |
| 10/17 | • | ling at | 5114 | Bit ∦6 | MW 9.0 | Vis. 34 | WL 6. | 0 0il 5% | |
| 10/18 | • | lling at | 5780 ' | Bit #6 | MW 9.1 | Vis. 32 | WL 6. | 2 Oil 5% | 36 |
| 10/19 | • | lling at | | Bit #7 | tripped | at 5828 | 3'. MW | 9.0 Vis. | 30 |
| 10/12 | | L 4.6 0: | | | _ | | L. J. ahoo | +) | |
| | | | | (Con | tinued o | n attac | ned shee | .) | |
| | | | | | | | | Set @ | Ft. |
| Subsurface | Safety Valve: I | Manu. and/T | Убе | | | | | | Ft. |
| ^ | | . /1\ \ .1 | . \ | J | | | | | |
| 18. There | y certify that to | 11111 | 4 04 | Pr | esident | n | ATF . | 10/23/81 | |
| SIGNED . | VY C | - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 | | TITLE | | | // · · · · · · · · · · · · · · · · · · | | |
| | 1 | 1/2 | (This | space for Fe | deral or State | office use) | | 0000000 | n con RECORI |
| | , | | | T(T) F | | | DATE | LIGHT | O FOR RECOR |
| APPROVED | BY S OF APPROVAL | ., IF ANY: | | _ ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | • | | | | 0.1000 |
| <u> </u> | | | | | | | | MAL | 1 1 3 1982 |
| | ~ | | | | | | | | |
| | \sim | | | *Con Incinuat | ions on Rever | se Side | | _ | NGTON DISTRICT |
| | | | | See matruct | on never | | | BY SA | - |

NMOCC

Sundry Report dated 10/23/81 Jicarilla 70-11 Chace Oil Company

| 10/20/81 | Drilling at 6479' | MW 9.1 | Vis. 36 | WL 6.0 | 0il 6% |
|----------|-------------------|--------|----------|---------|--------|
| 10/21/81 | Drilling at 6940' | MW 8.9 | Vis. 40 | WL 4.8 | |
| 10/22/81 | Drilling at 7290' | Bit #7 | MW 9∄ Vi | s, 50 W | L 7,0 |

Reached total depth of 7325' at 11 AM. Circulated 2 hours, Made 10 stand short trip. Back out of hole to log, Schlumberger ran induction and density log. Ran back into hole, pulled out of hole laying down. Preparing to rig up for 4 1/2" casing.