PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON*

(other) reseeding

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973			Approved. et Bureau No. 42–R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM 014023		
GEOLOGICAL SURVEY	6. IF INDIAN, A	LLOTTEE	OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME		
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME		
1. oil gas other	F-27-24-7		
well well other	9. WELL NO.		
2. NAME OF OPERATOR			· - · · · · · · · · · · · · · · · · · ·
Union Texas Petroleum Corporation	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Escrito Gallup		
P.O. Box 1290, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 27, T24N, R7W, NMPM		
below.) AT SUPEACE: 1770 E/South: 1660 E/Wort line	12. COUNTY OR PARISH 13. STATE		
AT SURFACE: 1770 F/South: 1660 F/West line AT TOP PROD. INTERVAL: same as above	Rio Arriba	PARISH	New Mexico
AT TOTAL DEPTH: Same as above	14 451 110		

change on Form 9-330.)

3. ADDRESS OF OPERATOR	Escrito Gallup		
P.O. Box 1290, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 27, T24N, R7W, NMPM		
AT SURFACE: 1770 F/South: 1660 F/West line AT TOP PROD. INTERVAL: same as above	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico		
AT TOTAL DEPTH: same as above	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6897 GR		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF			
REPAIR WELL	(NOTE: Report results of multiple completion or zone		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On September 10, 1983, reseeding was completed using BLM Seed Mix No. 2. The painting was completed using Brown Federal Standard No. 595a-30318.

Subsurface Safety Valve: Manu. and Typ	pe		Set @	Ft.
18. I hereby certify that the foregoing is SIGNED R. D. Mott	true and correct	Manager _ DATE	October 4, 1983	. -
	(This space for Federal or State office use	e)		
APPROVED BY	TITLE	DATE	CEPTED FOR RECOR	D

OCT 17 1983

