UNITED STATES

5. LEASE	SF 808566 A
F-040539	57-000300-11-

DEPARTMENT OF THE INTERIOR		SF-080539 - 5F-000300 A		
GEOLOGICAL SURVEY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS		7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill reservoir. Use Form 9-331-C for such propo	sals.)	8. FARM OR LEAS	SE NAM	AE.
1 all gon			Ca	yias
1. oil gas well other		9. WELL NO.	#1	
2. NAME OF OPERATOR				
Minel . Inc.	Curtis J. Little	10. FIELD OR WILL	_	
3. ADDRESS OF OPERATOR	P. O. Box 2487			pacito
27209 Kane Lane, Conrae TX	Farmington NM 87401	11. SEC., T., R., M	i., OR E	BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT Le	OCATION CLEARLY. See space 17	AREA Sec.	. 2-7	Γ25N-R3W
AT SURFACE:	2290'FNL, 1850'FEL	12. COUNTY OR P	ARISH	13. STATE
AT TOP PROD. INTERVAL:	same	Rio Arriba		N.M.
AT TOTAL DEPTH:	same	14. API NO.		
16 CUECK APPROPRIATE POY TO		-	າດ າ	2872
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 		30-039-22872 15. ELEVATIONS (SHOW DF, KDB, AND WD)		
REPORT, OR OTHER DATA		A STATE OF	•	• •
REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:	7329 KB		19'GL
TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF:	VE Cott	ecta	2 d
FRACTURE TREAT		" -		
SHOOT OR ACIDIZE		, 1982		
REPAIR WELL	I Voca	NOTE: Report resu	its of m	ultiple completion or zone
PULL OR ALTER CASING	\square $\beta_{i,0,i}$	change on	Form 9-	-330.)
MULTIPLE COMPLETE		OGICAL SUN.		
CHANGE ZONES	[] , e. GEON	IOTO ALL		
ABANDON*	U. FARMIN	NOTE: Report resu chapge on logical N. N.		
(other)				

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SPUD 8:00 pm 10-18-82. Drld 128'KB of 8-3/4" hole. Ran 116' of 7" 23# csg & at 126 B, 2% 8:30 a cemen 600 p plug

TD 6:00 pm 11-9-82. Log TD 3922'KB.

Log Tops: Ojo Alamo 3554, Kirtland 3652

Fruitland 3726, Pictured Cliffs 3829, Lewis 3886. RAN 122 jts 2-7/8" 6.5# EUE

CaCl & 1/4# floseal. Plug down am 10-19-82. Good circulation of t. WOC 12 hrs. Pressure tested to si. Held OK. Dev. 1/2 @ 126'. Drld 8:30 pm 10-19-82.	J-55 csg to 3921'KB. PBTD 3915'KB. Howco cemented w/535 sx 50-50 poz, 6% gel & 64 gilsonite and 50 sx Neat (995 cf slurry). Cement did not circul Plug down at 12:30 pm 11-10-82 w/410 psi. Held OK. Ran temp survey. Top cement at 220. WOC.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is frue and correct SIGNED Age (This space for Federal	
APPROVED BY TITLE	RCCEPTED FOR RECORD
NOV29 1982 See Instructions	NOV 26 1982