| UNITED STATES |
|----------------------------|
| DEPARTMENT OF THE INTERIOR |
| GEOLOGICAL SURVEY |

| UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY | 5. LEASE SF 078911 |
|---|---|
| | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | 7. UNIT AGREEMENT NAME Lindrith Unit 8. FARM OR LEASE NAME |
| 1. oil gas well x other | Lindrith Unit 9. WELL NO. |
| 2. NAME OF OPERATOR El Paso Natural Gas Company | 105 10. FIELD OR WILDCAT NAME S.Blanco Pictured Cliffs |
| 3. ADDRESS OF OPERATOR PO Box 289, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |
| below.) AT SURFACE: 900'S, 1080'W AT TOP PROD. INTERVAL: | sec. 2, T-24-N, R-3-W, NMPM 12. COUNTY OR PARISH 13. STATE Rio Arriba NM |
| AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14. API NO. |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6962'GL |
| MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly starincluding estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine 7-9-82 Spudded well. Drilled surface 24.0# K-55 surface casing, 131 | te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* hole. Ran 3 joints 8 5/8", |
| Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED | Set @Ft. ClerkATE7-16-82 |
| (This space for Federal or State of | 13527129 You hadolin |
| APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: | DATE |