UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-080594
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	None
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	Canyon Largo Unit
	8. FARM OR LEASE NAME
	Canyon Largo Unit
1. oil gas well other	9. WELL NO.
	320
2. NAME OF OPERATOR Bolack Minerals Company	10. FIELD OR WILDCAT NAME
	Devil's Fork-Gallup
3. ADDRESS OF OPERATOR P.O. Box 255, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	ARFA
	Sec. 1, T24N-R6W, NMPM
below.) AT SURFACE: 860' fN1, 1110' fW1	12. COUNTY OR PARISH 13. STATE
WITERVAL COMO	Rio Arriba N.M.
AT TOTAL DEPTH: same	14. API NO. 30-039-32133 15. ELEVATIONS (SHOW DF, KDB, AND WD) 699 Gr., 6706 KB est
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-039-32133
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
20 70000	69 Gr., 6706 KB est
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	VEP 1
TEST WATER SHUT-OFF	20 The state of th
FRACTURE TREAT SHOOT OR ACIDIZE	1983
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL APR *	(NOTE: Report results of multiple completion or zone SURVirange on Form 9–330.) OGICAL N. M.
PULL OR ALTER CASING	SURVirange on Form 9-330.)
MULTIPLE COMPLETE	OGICAN. M.
CHANGE ZONES	\mathcal{G}'
ABANDON* (other) First production	
(other) FIFSE PROPOSED OR COMPLETED OPERATIONS (Clearly sta	

measured and true vertical depths for all markers and zones pe

Operator installed production unit and tank and turned well on to clean-up and recover frac water at 10:00 a.m., 3/15/'83. Well unloaded oil in 15 min. and frac water in 30 min. In 24 hrs. with FTP of 60 psi and FCP of 220 psi well had produced approximately 26 bbls of oil , 5 bbls of frac water and was making 125 MCFPD. Well flowed approx. 12 hrs. more, produced an additional 13 bbls. oil and 3 bbls. of frac water and died. FTP 30 psi, FCP 300 psi. Shut well in for pressure build-up at noon, 3/17/'83 and have been unable to return to well since, due to weather and bad road conditions.

Subsurface Safety Valve: Manu. and Type	Set 🔞
SIGNED //	March 30, 1983
APPROVED BY JULY W. JULY TITLE MATING ASST- AM DATE CONDITIONS OF APPROVAL, IF ANY:	ACD FOR TECORD

APR 06 1983