

MERRION OIL & GAS CORPORATION

Canyon Largo Unit 338
Sec. 6, T24N, R6W
Rio Arriba Co., New Mexico

SLOPE TESTS


<u>Depth</u>	<u>Hole Deviation</u>
228	0
518	1/2
1021	1-3/4
1211	2-1/2
1462	2-1/2
1608	1-3/4
1850	2
2333	1-1/2
2836	1-1/2
2966	1-1/2
3496	1-1/4
3991	1-1/4
4492	1
5014	1-1/4
5510	1

RECEIVED
SEP 24 1984
OIL CON. DIV.
DIST. 3

State of New Mexico)
County of San Juan) ss

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn to before me this 21st day of August, 1984.



My Commission Expires March 25, 1988

Cheryl K. Simkins
Notary Public

